

Service Part #	Description		Service Part #	Description	
K07-0003	Front Windshield Glass, TLB	\$461.53	A00-0001	Outer Push Button Handle	\$66.00
K07-0005	Rear Window Glass, TLB	\$425.00	A00-0002	Left Interior Door Latch	\$56.67
K07-0001	Door Glass TLB	\$479.00	A00-0003	Right Interior Door Latch	\$56.67
K07-0002	Side Window Glass TLB	\$323.67	A00-0013	5MM Bushing	\$1.33
K07-0038	Glued in Lower Front Window	\$0.00	A00-0014	8MM Bushing	\$1.47
	Weatherstripping		A00-0018	Step Bolt, 1/4" x 1 1/2", MB	\$1.33
K07-0023	Front Windshield Weatherstripping, TLB	\$58.67	A00-0019	Step Bolt, 1/4" x 1", MB	\$1.33
K07-0022	Rear Window Weatherstripping, TLB	\$58.67	A00-0020	Step Bolt, 1/4" x 1 1/4", MB	\$1.33
K07-0020	Door Weatherstripping, TLB	\$58.67	A00-0021	Flange Nut, 1/4", MB	\$0.67
K07-0018	Side Window Weatherstripping, TLB	\$51.33	A00-0039	Door Hinge Weldment, Left Upper	\$36.67
	Frames		A00-0040	Cab Door Grab Handle	\$66.00
K07-0006	Left Door Frame Weldment, Back Hoe	\$425.00	A00-0042	Door Hinge Weldment, Right Upper	\$36.67
K07-0021	Right Door Frame Weldment, Back Hoe	\$425.00	A00-0044	Left Side Window Hinge Weldment	\$20.67
	Full Assembly's		A00-0046	Right Side Window Hinge Weldment	\$20.67
K07-0035	Complete Left Door Assembly TLB Cab	\$952.20	A00-0065	On-off Rocker Switch	\$35.33
K07-0036	Complete Right Door Assembly TLB Cab	\$952.20	A00-0084	Gas Shock, Standard	\$36.67
K07-0032	Complete LH Side Window Assembly, TLB	\$674.00	A00-0085	Ball Stud for shock with 5/16" flange nut	\$2.67
K07-0033	Complete RH Side Window Assembly, TLB	\$674.00	A00-0129	Keys (Pair)	\$7.33
			A00-0131	Exterior Fuel Cap	\$51.33
			A00-0141	Exterior Mirror, Round, 6", Single	\$55.67
			A00-0228	Door Hinge Weldment, Left Lower	\$32.33
			A00-0229	Door Hinge Weldment, Right Lower	\$32.33
			A00-0289	Grab Handle Endcap, Black Plastic	\$13.00

Note: To ensure the correct parts, it is advised you provide your serial number from your cab before ordering.