

**Toro Reel Master 5210, 5410, 5510, and 5610  
Product Specifications and Pricing**



**Base 4-Post ROPS:**

- Solid-welded 4-post ROPS frame
- Solid-welded steel roof canopy
- Brush guard with integrated light bar at the front and rear
- Fully upholstered headliner
- Powder coated all black paint finish
- Quick installation
- ROPS meets OSHA 1928 and CSA B352 ROPS requirements

**Optional Golf Ball Mesh Protection Package:**

- Push button door handles with key lock
- Lift off door hinges
- 1" square 16GA mesh
- Door frames and rear window are covered with welded mesh
- Doors can open when decks are raised
- Powder coated black door frames

**Windshield Options:**

- Polycarbonate windshield
- Tempered glass windshield with front wiper mounting provisions available
- Front radial wiper with tempered glass option only
- AS-1 flat glass laminated windshield with wiper provisions
- Front wiper washer

**Available Options:**

- Powder coat red frame finish w/black doors
- Rear window mesh only
- Front Worklights (LED available)
- Rear Worklight (LED available)
- Interior Mirror



Item Description	MSRP	Part #
<b>Base Unit</b>		
Base 4-post ROPS	\$1,080.00	To5210-001
Custom Colour Toro Red (black doors)	\$80.00	To5210-023
<b>Golf Protection</b>		
Heavy Duty Golf Ball Mesh Package	\$1,200.00	To5210-022
Polycarbonate Windshield	\$260.00	To5210-003
Rear Window Mesh Only Kit	\$110.00	To5210-020
<b>Glass Windshield</b>		
Tempered Glass Windshield (with Wiper holes)	\$445.00	To5210-004
Front Wiper (Tempered Glass Only)	\$370.00	To5210-005
Front Wiper Washer	\$130.00	To5210-016
AS-1 Flat Glass Option (wiper provisions)	\$340.00	To5210-019
<b>Lighting Options</b>		
Front Worklights	\$130.00	To5210-006
Rear Worklamp	\$80.00	To5210-007
Front LED Worklights	\$270.00	To5210-017
Rear LED Worklamp	\$260.00	To5210-018
<b>Mirror Options</b>		
Interior Mirror	\$50.00	To5210-014

Tektite Manufacturing Inc.  
Box 639, 24157 Highway # 3  
Winkler MB R6W 4A8 Canada  
P 204-331-3463  
F 204-331-4159

Prices effective February 1, 2016. Freight and installation are not included.