

Service Part #	Description		Service Part #	Description	
K09-0001	Opening Front Windshield Glass	\$468.67	A00-0001	Outer Push Button Handle	\$66.00
K10-0001	Rear Window Glass	\$417.53	A00-0002	Left Interior Door Latch	\$56.67
K10-0008	Door Glass	\$461.53	A00-0003	Right Interior Door Latch	\$56.67
K10-0007	Side Window Glass	\$307.67	A00-0013	5MM Bushing	\$1.33
K09-0002	Lower Front Window	\$198.00	A00-0014	8MM Bushing	\$1.47
	Weatherstripping		A00-0018	Step Bolt, 1/4" x 1 1/2", MB	\$1.33
K09-0007	Front Windshield Weatherstripping	\$58.67	A00-0019	Step Bolt, 1/4" x 1", MB	\$1.33
K10-0006	Rear Window Weatherstripping	\$58.67	A00-0020	Step Bolt, 1/4" x 1 1/4", MB	\$1.33
K10-0009	Door Weatherstripping	\$66.00	A00-0021	Flange Nut, 1/4", MB	\$0.67
K10-0010	Side Window Weatherstripping	\$46.33	A00-0039	Door Hinge Weldment, Left Upper	\$36.67
K09-0025	Lower Front Window Weatherstripping	\$29.33	A00-0040	Cab Door Grab Handle	\$66.00
	Frames		A00-0042	Door Hinge Weldment, Right Upper	\$36.67
K10-0002	Left Door Frame Weldment	\$381.00	A00-0044	Left Side Window Hinge Weldment	\$20.67
K10-0003	Right Door Frame Weldment	\$381.00	A00-0046	Right Side Window Hinge Weldment	\$20.67
	Full Assembly's		A00-0065	On-off Rocker Switch	\$35.33
K10-0004	Complete Left Door Assembly	\$937.53	A00-0084	Gas Shock, Standard	\$36.67
K10-0005	Complete Right Door Assembly	\$937.53	A00-0085	Ball Stud for shock with 5/16" flange nut	\$2.67
K10-0012	Complete Left Side Window Assembly	\$630.00	A00-0129	Keys (Pair)	\$7.33
K10-0013	Complete Right Side Window Assembly	\$630.00	A00-0131	Exterior Fuel Cap	\$51.33
K10-0016	Complete Front Window Assembly w/wiper	\$1,025.33	A00-0141	Exterior Mirror, Round, 6", Single	\$55.67
			A00-0228	Door Hinge Weldment, Left Lower	\$32.33
			A00-0229	Door Hinge Weldment, Right Lower	\$32.33
			A00-0289	Grab Handle Endcap, Black Plastic	\$13.00

Note: To ensure the correct parts, it is advised you provide your serial number from your cab before ordering.